

GKN Aerospace Sweden AB (GAS)

GAS External LAB List

VOLS:10177303 issue 4

Note: This list is only valid on GKN Aerospace Sweden AB, designed products controlled by GKN Aerospace Sweden AB Specification VOLS:10071573 (Control of materials and methods).

*If marked with an X, there is a restriction to this approval. Please contact GAS for more information.

| GAS Source no | Source Name | Source Address | Source Country | Process | Sub Process (Nadcap codes) | Material Group | Restrictions* |
|---------------|---------------------------------|---|----------------|---|---------------------------------------|--|---------------|
| TBD | ACUREN | 4374 Lancaster Highway, Richburg, South Carolina 29729 | US | Mechanical Testing | A, B, C | | |
| TBD | ACUREN | 4374 Lancaster Highway, Richburg, South Carolina 29729 | US | Hardness | M1, M2 | | |
| TBD | ACUREN | 4374 Lancaster Highway, Richburg, South Carolina 29729 | US | Metallography & Microhardness | L, L8 | | |
| TBD | ACUREN | 4374 Lancaster Highway, Richburg, South Carolina 29729 | US | Mechanical Testing Specimen Preparation | Z, Z1 | | |
| TBD | ACUREN | 4374 Lancaster Highway, Richburg, South Carolina 29729 | US | Corrosion | Q | | |
| TBD | AMPP SERVI | 11 Halcyon Court St Margarets Way, Huntingdon PE29 6DG UK | GB | Metallography & Microhardness | L8, L9 | | |
| TBD | Allvac Lockport | 695 Ohio St, Lockport, New York 14094, United States | US | Chemical Testing | G4, G5, S, F3, G3, G1 | Co Base, Ni Base, Fe Base High Alloy, Fe Base, Low Alloy | |
| 0000036998 | Allvac Monroe | 2020 Ashcraft Ave, 28110 Monroe NC | US | Mechanical Testing | A, B, C | | |
| 0000036998 | Allvac Monroe | 2020 Ashcraft Ave, 28110 Monroe NC | US | Hardness | M1, M2 | | |
| 0000036998 | Allvac Monroe | 2020 Ashcraft Ave, 28110 Monroe NC | US | Metallography & Microhardness | L, L8, XL | | |
| 0000036998 | Allvac Monroe | 2020 Ashcraft Ave, 28110 Monroe NC | US | Mechanical Testing Specimen Preparation | Z | | |
| 0000036998 | Allvac Monroe | 2020 Ashcraft Ave, 28110 Monroe NC | US | Chemical Testing | F2, F3, G1, G2, G3, G4, G5, S, W2 | Co Base, Fe Base High Alloy, Fe Base Low Alloy, Ni Base, Ti Base | |
| TBD | Allegheny Ludlum | 100 River Road, 15014 Brackenridge PA US | US | Mechanical Testing | A, C, XN | | |
| TBD | Allegheny Ludlum | 100 River Road, 15014 Brackenridge PA US | US | Hardness | M1, M2, M3 | | |
| TBD | Allegheny Ludlum | 100 River Road, 15014 Brackenridge PA US | US | Metallography & Microhardness | L, L1, L5, L7, L8, XL | | |
| TBD | Allegheny Ludlum | 100 River Road, 15014 Brackenridge PA US | US | Heat Treating | XG | | |
| TBD | Allegheny Ludlum | 100 River Road, 15014 Brackenridge PA US | US | Mechanical Testing Specimen Preparation | Z | | |
| TBD | Allegheny Ludlum | 100 River Road, 15014 Brackenridge PA US | US | Chemical Testing | F1, F2, F3,G1, G2, G3, G4, G5, S, W2 | Ti Base, Fe Base High Alloy, Ni Base | |
| TBD | ATI Allegheny Ludlum | 1300 Pacific avenue, Natrona Heights, PA 15065 - 1147 USA | US | Mechanical Testing | A, XN | | |
| TBD | ATI Allegheny Ludlum | 1300 Pacific avenue, Natrona Heights, PA 15065 - 1147 USA | US | Chemical Testing | F1, F2, F3, G1, G2, G3, G4, G5, S, W2 | | |
| TBD | ATI Allegheny Ludlum | 1300 Pacific avenue, Natrona Heights, PA 15065 - 1147 USA | US | Hardness Testing | M1, M2 | | |
| TBD | ATI Allegheny Ludlum | 1300 Pacific avenue, Natrona Heights, PA 15065 - 1147 USA | US | Metallography & Microhardness | L, L1, L3, L7, XL | | |
| TBD | ATI Wah Chang | 1600 Old Salem Rd NE, 97321-0460 Albany OR | US | Chemical Testing | G4, G1, F1, G2, F2, G3, V2 | Ti Base | |
| 0000037942 | Barnes Aerospace Ogden Division | 1025 South Depot Drive Ogden, 84401, Utah | US | Hardness | M2 | | |
| 0000037942 | Barnes Aerospace Ogden Division | 1025 South Depot Drive Ogden, 84401, Utah | US | Metallography & Microhardness | L8, L, XL, L7 | | |
| 0000037942 | Barnes Aerospace Ogden Division | 1025 South Depot Drive Ogden, 84401, Utah | US | Corrosion | Q | | |
| 0000037942 | Barnes Aerospace Ogden Division | 1025 South Depot Drive Ogden, 84401, Utah | US | Mechanical Testing Specimen Preparation | Z | | |

| | | | | | | | |
|------------|---------------------------------|--|-----|---|--|--|--|
| 0000037942 | Barnes Aerospace Ogden Division | 1025 South Depot Drive Ogden, 84401 , Utah | US | Chemical Testing | G2 | Ti Base | |
| TBD | Bohler Edelstahl GmbH & CO KG | Mariazellerstrasse 25 8605 Kapfenberg, Austria | AUT | Mechanical Testing | A, B, C, N | | |
| TBD | Bohler Edelstahl GmbH & CO KG | Mariazellerstrasse 25 8605 Kapfenberg, Austria | AUT | Hardness | M1, M2, M3 | | |
| TBD | Bohler Edelstahl GmbH & CO KG | Mariazellerstrasse 25 8605 Kapfenberg, Austria | AUT | Metallography & Microhardness | LS, L10, L8, L, XL | | |
| TBD | Bohler Edelstahl GmbH & CO KG | Mariazellerstrasse 25 8605 Kapfenberg, Austria | AUT | Heat Treating | XG | | |
| TBD | Bohler Edelstahl GmbH & CO KG | Mariazellerstrasse 25 8605 Kapfenberg, Austria | AUT | Chemical Testing | G1, F2, G3, G5 | | |
| TBD | Bohler Edelstahl GmbH & CO KG | Mariazellerstrasse 25 8605 Kapfenberg, Austria | AUT | Corrosion | Q1 | | |
| TBD | Cannon Muskegon Corp. | 2875 Lincoln St, Muskegon, Michigan 49441, United States | US | Chemical Testing | G1, G3, G4, G5, F2, V2, S, W2, W1, F3 | Co Base, Ni Base, Fe Base Low Alloy, Fe Base High Alloy | |
| TBD | Carpenter Powder Products | 600 Mayer St, Bridgeville, Pennsylvania 15017-2705 | US | Chemical Testing | G1, G2, G3, G4, G5, F2 | Co Base, Fe Base High Alloy, Fe Base Low Alloy, Ni Base, Ti Base | |
| 0000041677 | Carpenter Technology Corp. | 101 W Bern St, 19601 Reading PA | US | Mechanical Testing | A, B, C, N, XN | | |
| 0000041677 | Carpenter Technology Corp. | 101 W Bern St, 19601 Reading PA | US | Hardness | M2, M1, M3 | | |
| 0000041677 | Carpenter Technology Corp. | 101 W Bern St, 19601 Reading PA | US | Metallography & Microhardness | L2, L, XL, L1, L5 | | |
| 0000041677 | Carpenter Technology Corp. | 101 W Bern St, 19601 Reading PA | US | Heat Treating | Specimen Heat Treating | | |
| 0000041677 | Carpenter Technology Corp. | 101 W Bern St, 19601 Reading PA | US | Mechanical Testing Specimen Preparation | Z | | |
| 0000041677 | Carpenter Technology Corp. | 101 W Bern St, 19601 Reading PA | US | Chemical Testing | D, F2, F3, G1, G3, G4, G5, S, V, W1, W2 | Co Base, Fe Base High Alloy, Fe Base Low Alloy, Ni Base | |
| 0000041677 | Carpenter Technology Corp. | 101 W Bern St, 19601 Reading PA | US | Corrosion | Q, Q1 | | |
| 0000043898 | Connecticut Metallurgical Inc | 100 Prestige PK, East Hartford, Connecticut06108 | US | Mechanical Testing | A, B, C, XN | | |
| 0000043898 | Connecticut Metallurgical Inc | 100 Prestige PK, East Hartford, Connecticut06108 | US | Hardness | M2 | | |
| 0000043898 | Connecticut Metallurgical Inc | 100 Prestige PK, East Hartford, Connecticut06108 | US | Metallography & Microhardness | L6, L1, L2, L8, L, XL, L5, L7 | | |
| 0000043898 | Connecticut Metallurgical Inc | 100 Prestige PK, East Hartford, Connecticut06108 | US | Heat Treating | Specimen Heat Treating | | |
| 0000043898 | Connecticut Metallurgical Inc | 100 Prestige PK, East Hartford, Connecticut06108 | US | Metallographic Evaluation of welds | Welder, Electron beam, Laser, Resistance, Fusion | | |
| 0000043898 | Connecticut Metallurgical Inc | 100 Prestige PK, East Hartford, Connecticut06108 | US | Chemical Testing | G1, F2, G3, G5 | Co Base, Fe Base High Alloy, Fe Base Low Alloy, Ni Base, Ti Base, Cu Base, Al Base | |
| 0000043898 | Connecticut Metallurgical Inc | 100 Prestige PK, East Hartford, Connecticut06108 | US | Corrosion | Q, Q1 | | |
| TBD | Dickson Testing Co Inc | 11126 Palmer Ave, 90280 South Gate CA | US | Mechanical Testing | A, B, C, N, XN | | |
| TBD | Dickson Testing Co Inc | 11126 Palmer Ave, 90280 South Gate CA | US | Hardness | M1, M2 | | |
| TBD | Dickson Testing Co Inc | 11126 Palmer Ave, 90280 South Gate CA | US | Metallography & Microhardness | L6, L1, L9, L2, L8, L, XL, L4, L5, L7, L3 | | |
| TBD | Dickson Testing Co Inc | 11126 Palmer Ave, 90280 South Gate CA | US | Heat Treating | Specimen Heat Treating | | |
| TBD | Dickson Testing Co Inc | 11126 Palmer Ave, 90280 South Gate CA | US | Mechanical Testing Specimen Preparation | Z, Z1, Z3 | | |
| TBD | Dickson Testing Co Inc | 11126 Palmer Ave, 90280 South Gate CA | US | Chemical Testing | F2, F3, G1, G2, G3, G4, G5, W2 | Co Base, Fe Base High Alloy, Fe Base Low Alloy, Ni Base, Cu Base, Al Base, Ti Base | |

| | | | | | | |
|------------|-----------------------------|---|----|---|--|---|
| TBD | Dickson Testing Co Inc | 11126 Palmer Ave, 90280 South Gate CA | US | Corrosion | Q, Q1 | |
| 0000012404 | Dirats Laboratories | 41 Airport Road, 01086-0039 Westfield MA | US | Mechanical Testing | A, B, C, N, XN, Hydrogen Embrittlement | |
| 0000012404 | Dirats Laboratories | 41 Airport Road, 01086-0039 Westfield MA | US | Hardness | M1, M2 | |
| 0000012404 | Dirats Laboratories | 41 Airport Road, 01086-0039 Westfield MA | US | Metallography & Microhardness | L, L6, L1, L9, L2, L8, L5, XL, L3, L4, L5, L5X, L7, L10 | |
| 0000012404 | Dirats Laboratories | 41 Airport Road, 01086-0039 Westfield MA | US | Heat Treating | Specimen Heat Treating | |
| 0000012404 | Dirats Laboratories | 41 Airport Road, 01086-0039 Westfield MA | US | Mechanical Testing Specimen Preparation | Z3, Z, Z1, Z4 | |
| 0000012404 | Dirats Laboratories | 41 Airport Road, 01086-0039 Westfield MA | US | Chemical Testing | G1, G4, G2, F2, F3, V2, S, G3, G5, W2 | Co Base, Fe Base High Alloy, Fe Base Low Alloy, Ni Base, Ti Base, Cu Base, Al Base, Mg Base |
| 0000012404 | Dirats Laboratories | 41 Airport Road, 01086-0039 Westfield MA | US | Corrosion | Q, Q1 | |
| 0000012404 | Dirats Laboratories | 41 Airport Road, 01086-0039 Westfield MA | US | Metallographic Evaluation of welds | Electron Beam / Laser Welds, Welder/Welding Operator Qualifications, fusion welds, electron beam/laser welds, resistance welds, Bend Test welder/welding operator qualification welds, Bend Test fusion welds, Bend Test Electron Beam and Laser | |
| TBD | Durkee Testing Laboratories | 15700 Texaco Street, Paramount, CA 90723-0400 | US | Mechanical Testing | Metallurgical Evaluation of Welder/Welding Operator Qualifications | |
| TBD | Durkee Testing Laboratories | 15700 Texaco Street, Paramount, CA 90723-0400 | US | Hardness | Metallurgical Evaluation of fusion welds | |
| TBD | Durkee Testing Laboratories | 15700 Texaco Street, Paramount, CA 90723-0400 | US | Metallography & Microhardness | Metallurgical Evaluation of electron beam/laser welds | |
| TBD | Durkee Testing Laboratories | 15700 Texaco Street, Paramount, CA 90723-0400 | US | Heat Treating | Metallurgical Evaluation of resistance welds | |
| TBD | Durkee Testing Laboratories | 15700 Texaco Street, Paramount, CA 90723-0400 | US | Mechanical Testing Specimen Preparation | Bend Test Evaluation of welder/welding operator qualification welds | |
| TBD | Durkee Testing Laboratories | 15700 Texaco Street, Paramount, CA 90723-0400 | US | Chemical Testing | Bend Test Evaluation of fusion welds | Co Base, Fe Base High Alloy, Fe Base Low Alloy, Ni Base, Ti Base, Cu Base, Al Base, Mg Base |
| TBD | Durkee Testing Laboratories | 15700 Texaco Street, Paramount, CA 90723-0400 | US | Corrosion | Bend Test Evaluation of Electron Beam and Laser | |
| 12173 | Doncasters Blaenavon | Forgeside Blaenavon NP4 9XG GB | GB | Metallography & Microhardness | L | |
| 12173 | Doncasters Blaenavon | Forgeside Blaenavon NP4 9XG GB | GB | Hardness | M1 | |
| TBD | Element Charlotte | 1200 Westing House Blvd Ste A, 28273-6313 Charlotte NC US | US | Mechanical Testing | A, B, C, N, XN | |
| TBD | Element Charlotte | 1200 Westing House Blvd Ste A, 28273-6313 Charlotte NC US | US | Hardness | M1, M2, M3 | |
| TBD | Element Charlotte | 1200 Westing House Blvd Ste A, 28273-6313 Charlotte NC US | US | Metallography & Microhardness | L, L1, L2, L3, L5, L6, L7, XL | |
| TBD | Element Charlotte | 1200 Westing House Blvd Ste A, 28273-6313 Charlotte NC US | US | Mechanical Testing Specimen Preparation | Z, Z1, Z3, Z4 | |

| | | | | | | | |
|------------|------------------------|--|----|---|--|---|--|
| TBD | Element Charlotte | 1200 Westing House Blvd Ste A, 28273-6313 Charlotte NC US | US | Chemical Testing | F3, G1, G2, G5 | Co Base, Fe Base High Alloy, Fe Base Low Alloy, Ni Base, Ti Base, Cu Base, Al Base | |
| TBD | Element Charlotte | 1200 Westing House Blvd Ste A, 28273-6313 Charlotte NC US | US | Corrosion | Q1 | | |
| 0000662697 | Element Cincinnati | 1245 Hillsmith Dr, 45215 Cincinnati OH US | US | Mechanical Testing | A, B, C, Y, O, P | | |
| TBD | Element Cincinnati | 12077 Mosteller Rd, 45241-1528 Cincinnati, Ohio US | US | Mechanical Testing Specimen Preparation | Z, Z1, Z2, Z4 | | |
| 0000044533 | Element Huntington | 15062 Bolsa Chica 92649 Huntington Beach CA | US | Mechanical Testing | A, B, C, N, XN | | |
| 0000044533 | Element Huntington | 15062 Bolsa Chica 92649 Huntington Beach CA | US | Hardness | M1, M2, M3 | | |
| 0000044533 | Element Huntington | 15062 Bolsa Chica 92649 Huntington Beach CA | US | Metallography & Microhardness | L6, L1, L9, L2, L8, L, XL, L4, L5, L3, L7 | | |
| 0000044533 | Element Huntington | 15062 Bolsa Chica 92649 Huntington Beach CA | US | Heat Treating | Specimen Heat Treating | | |
| 0000044533 | Element Huntington | 15062 Bolsa Chica 92649 Huntington Beach CA | US | Mechanical Testing Specimen Preparation | Z, Z1, Z2, Z3, Z4 | | |
| 0000044533 | Element Huntington | 15062 Bolsa Chica 92649 Huntington Beach CA | US | Chemical Testing | F2, F3, G1, G2, G3, G4, G5, S, W2 | Mg Base, Ti Base, Cu Base, Fe Base Low Alloy, Fe Base High Alloy, Co Base, Ni Base, Al Base | |
| 0000044533 | Element Huntington | 15062 Bolsa Chica 92649 Huntington Beach CA | US | Corrosion | Q, Q1 | | |
| 0000044534 | Element Newtown | 2 Pheasant Run. 18940 Newtown PA | US | Mechanical Testing | A, B, C, N, XN | | |
| 0000044534 | Element Newtown | 2 Pheasant Run. 18940 Newtown PA | US | Hardness | M1, M2 | | |
| 0000044534 | Element Newtown | 2 Pheasant Run. 18940 Newtown PA | US | Metallography & Microhardness | L, L1, L2, L3, L5, L6, L7, L8, L9, L10, L5, XL | | |
| 0000044534 | Element Newtown | 2 Pheasant Run. 18940 Newtown PA | US | Specimen Heat Treating | | | |
| 0000044534 | Element Newtown | 2 Pheasant Run. 18940 Newtown PA | US | Mechanical Testing Specimen Preparation | Z, Z3 | | |
| 0000044534 | Element Newtown | 2 Pheasant Run. 18940 Newtown PA | US | Chemical Testing | F3, G1, G2, G3, G4, G5 | Ti Base, Cu Base, Fe Base Low Alloy, Fe Base High Alloy, Co Base, Al Base | |
| 0000044534 | Element Newtown | 2 Pheasant Run. 18940 Newtown PA | US | Corrosion | Q, Q1 | | |
| TBD | Exova Inc. Laboratory | 194 Internationale Blvd, 60139-2094 Glendale Heights IL US | US | Mechanical Testing | A, B, C, N, XN | | |
| TBD | Exova Inc. Laboratory | 194 Internationale Blvd, 60139-2094 Glendale Heights IL US | US | Hardness | M1, M2 | | |
| TBD | Exova Inc. Laboratory | 194 Internationale Blvd, 60139-2094 Glendale Heights IL US | US | Metallography & Microhardness | L, L1, L2, L3, L4, L5, L6, L7, L8, L9, XL | | |
| TBD | Exova Inc. Laboratory | 194 Internationale Blvd, 60139-2094 Glendale Heights IL US | US | Heat Treating | XG | | |
| TBD | Exova Inc. Laboratory | 194 Internationale Blvd, 60139-2094 Glendale Heights IL US | US | Mechanical Testing Specimen Preparation | Z, Z3, Z4 | | |
| TBD | Exova Inc. Laboratory | 194 Internationale Blvd, 60139-2094 Glendale Heights IL US | US | Chemical Testing | F2, F3, G1, G2, G3, G4, G5 | | |
| TBD | Exova Inc. Laboratory | 194 Internationale Blvd, 60139-2094 Glendale Heights IL US | US | Corrosion | Q | | |
| TBD | Exova Inc. Los Angeles | 1005 Freeman Ave, Santa Fe Springs, 90670 California | US | Mechanical Testing | C, XN | | |
| TBD | Exova Inc. Los Angeles | 1005 Freeman Ave, Santa Fe Springs, 90670 California | US | Chemical Testing | F2, F3, G1, G2, G3, G4, G5, W2 | Co Base, Fe Base High Alloy, Fe Base Low Alloy, Ni Base, Ti Base, Cu Base, Al Base, S | |
| 0000044652 | Exova Inc. Mexico | Col. Privadas de Sta Catarina Carr. Monterrey-Saltillo No 3279-B, Santa Catarina NL C.P. 66367 | MX | Mechanical Testing | A, B, C, N | | |
| 0000044652 | Exova Inc. Mexico | Col. Privadas de Sta Catarina Carr. Monterrey-Saltillo No 3279-B, Santa Catarina NL C.P. 66367 | MX | Hardness | M1, M2 | | |

| | | | | | | | |
|------------|---------------------------|--|----|---|---------------------------|--|---|
| 0000044652 | Exova Inc. Mexico | Col. Privadas de Sta CatarinaCarr. Monterrey-Salttillo No 3279-B, Santa Catarina NL C.P. 66367 | MX | Metallography & Microhardness | L, L2, L7, L8, XL | | |
| 0000044652 | Exova Inc. Mexico | Col. Privadas de Sta CatarinaCarr. Monterrey-Salttillo No 3279-B, Santa Catarina NL C.P. 66367 | MX | Heat Treating | XG | | |
| 0000044652 | Exova Inc. Mexico | Col. Privadas de Sta CatarinaCarr. Monterrey-Salttillo No 3279-B, Santa Catarina NL C.P. 66367 | MX | Mechanical Testing Specimen Preparation | Z | | |
| 12399 | Exova Material Technology | Box 1340, 58113 Linköping, Sweden | SE | Metallography & Microhardness | L, LS, L7 | | |
| 12399 | Exova Material Technology | Box 1340, 58113 Linköping, Sweden | SE | Hardness | M1, M2, M3 | | |
| 12399 | Exova Material Technology | Box 1340, 58113 Linköping, Sweden | SE | Corrosion | Q | | |
| TBD | Exova Mississauga | 2395 Speakman Drive ON L5K 1B3 Mississauga CA | CA | Mechanical Testing | A, B | | |
| TBD | Exova Mississauga | 2395 Speakman Drive ON L5K 1B3 Mississauga CA | CA | Mechanical Testing Specimen Preparation | Z, Z1 | | |
| TBD | Exova Newcastle | Shields Rd, NE62YD Newcastle upon Tyne, UK | GB | Mechanical Testing | A,XA,C,B | | |
| TBD | Exova Newcastle | Shields Rd, NE62YD Newcastle upon Tyne, UK | GB | Mechanical Testing Specimen Preparation | Z | | |
| TBD | Exova Portland | 4949 SE Johnson Creek Blvd, 97222 Portland,OR | US | Mechanical Testing | A, B, C, N | | |
| TBD | Exova Portland | 4949 SE Johnson Creek Blvd, 97222 Portland,OR | US | Hardness | M2, M3 | | |
| TBD | Exova Portland | 4949 SE Johnson Creek Blvd, 97222 Portland,OR | US | Metallography & Microhardness | L, L1, L2, L4, L7, L8, L9 | | |
| TBD | Exova Portland | 4949 SE Johnson Creek Blvd, 97222 Portland,OR | US | Chemical Testing | F3, G1, G2, G3, G4, G5, S | | |
| TBD | Exova Portland | 4949 SE Johnson Creek Blvd, 97222 Portland,OR | US | Mechanical Testing Specimen Preparation | Z, Z3 | | |
| TBD | Exova Limited Somerset | Showground Business Park, TA6 6LS Bridgewater Somerset | GB | Mechanical Testing | A, B, N, XN | | |
| TBD | Exova Limited Somerset | Showground Business Park, TA6 6LS Bridgewater Somerset | GB | Hardness | M1, M2, M3 | | |
| TBD | Exova Limited Somerset | Showground Business Park, TA6 6LS Bridgewater Somerset | GB | Metallography & Microhardness | L, L3, L7, L8, XL | | |
| TBD | Exova Limited Somerset | Showground Business Park, TA6 6LS Bridgewater Somerset | GB | Mechanical Testing Specimen Preparation | Z | | |
| TBD | Exova SRO | Podnikatelska 39, 30100 Plzen | CZ | Mechanical Testing | A, B, C, N, XA | | |
| TBD | Exova SRO | Podnikatelska 39, 30100 Plzen | CZ | Hardness | M1, M2, M3 | | |
| TBD | Exova SRO | Podnikatelska 39, 30100 Plzen | CZ | Metallography & Microhardness | L, L1, L5, L8, XL | | |
| TBD | Exova SRO | Podnikatelska 39, 30100 Plzen | CZ | Chemical Testing | G2 | | |
| TBD | Exova SRO | Podnikatelska 39, 30100 Plzen | CZ | Heat Treating | XN | | |
| TBD | Exova Limited Dudley | 182 Halesowen Road, DY2 9PL Netherton Dudley, UK | GB | Mechanical Testing | A, B, C, N | | |
| TBD | Exova Limited Dudley | 182 Halesowen Road, DY2 9PL Netherton Dudley, UK | GB | Hardness | M1 | | |
| TBD | Exova Limited Dudley | 182 Halesowen Road, DY2 9PL Netherton Dudley, UK | GB | Metallography & Microhardness | L, L7, XL | | |
| TBD | Exova Limited Dudley | 182 Halesowen Road, DY2 9PL Netherton Dudley, UK | GB | Mechanical Testing Specimen Preparation | Z, Z3 | | |
| 0000041799 | Fountain Plating Inc. | 492 Prospect Avenue, West Springfield, MA 01089, Unites States | US | Chemical processing | | | X |
| 0000002270 | GKN Aerospace Sweden AB | Materials and processes, Flygmotorvägen, 46131 Trollhättan, Sweden | SE | Mechanical Testing | O, Y, XE | | |

| | | | | | | |
|------------|----------------------------------|--|----|---|---|---|
| 000002270 | GKN Aerospace Sweden AB | Materials and processes, Flygmotorvägen, 46131 Trollhättan, Sweden | SE | Hardness | M1, M2, M3 | |
| 000002270 | GKN Aerospace Sweden AB | Materials and processes, Flygmotorvägen, 46131 Trollhättan, Sweden | SE | Metallography & Microhardness | L, L1, L2, L3, L5, L7, L8, L9, L10, L11, XL | |
| TBD | Gloria Material Technology Corp. | 35 Hsin Chung Rd, Hsin Ying Tainan, 730, Taiwan | TW | Mechanical Testing | A | |
| TBD | Gloria Material Technology Corp. | 35 Hsin Chung Rd, Hsin Ying Tainan, 730, Taiwan | TW | Hardness | M1, M2 | |
| TBD | Gloria Material Technology Corp. | 35 Hsin Chung Rd, Hsin Ying Tainan, 730, Taiwan | TW | Metallography & Microhardness | L, XL | |
| TBD | Gloria Material Technology Corp. | 35 Hsin Chung Rd, Hsin Ying Tainan, 730, Taiwan | TW | Chemical Testing | F3, G1, G3, G4, G5, S | Fe Base High Alloy, Fe Base Low Alloy |
| TBD | Gloria Material Technology Corp. | 35 Hsin Chung Rd, Hsin Ying Tainan, 730, Taiwan | TW | Mechanical Testing Specimen Preparation | Z | |
| TBD | Gloria Material Technology Corp. | 35 Hsin Chung Rd, Hsin Ying Tainan, 730, Taiwan | TW | Specimen Heat Treating | | |
| 931112 | Haynes International Inc. | 2000 W Deffenbaugh Street, 46902 Kokomo IN US | US | Mechanical Testing | A, B, C, XN | |
| 931112 | Haynes International Inc. | 2000 W Deffenbaugh Street, 46902 Kokomo IN US | US | Hardness | M2 | |
| 931112 | Haynes International Inc. | 2000 W Deffenbaugh Street, 46902 Kokomo IN US | US | Metallography & Microhardness | LS ,L2,L,XL,L7 | |
| 931112 | Haynes International Inc. | 2000 W Deffenbaugh Street, 46902 Kokomo IN US | US | Heat Treating | XG | |
| 931112 | Haynes International Inc. | 2000 W Deffenbaugh Street, 46902 Kokomo IN US | US | Mechanical Testing Specimen Preparation | Z | |
| 931112 | Haynes International Inc. | 2000 W Deffenbaugh Street, 46902 Kokomo IN US | US | Chemical Testing | D,G1,S,F2,F3,G3,G5 | |
| 0000012217 | Haynes International Inc. | 1020 W Park Ave, Kokomo, Indiana 46904-9013 | US | Mechanical Testing | A, B, C, N, XN | |
| 0000012217 | Haynes International Inc. | 1020 W Park Ave, Kokomo, Indiana 46904-9013 | US | Metallography & Microhardness | L, L2, L7, L5 | |
| TBD | IMR KHA-Portland LLC | 5687-A SE International Way, 97222 Portland OR US | US | Mechanical Testing | A, B, C, N, XN | |
| TBD | IMR KHA-Portland LLC | 5687-A SE International Way, 97222 Portland OR US | US | Hardness | M1, M2 | |
| TBD | IMR KHA-Portland LLC | 5687-A SE International Way, 97222 Portland OR US | US | Metallography & Microhardness | L, L1, L2, L5, L6, L7, L8, L9 | |
| TBD | IMR KHA-Portland LLC | 5687-A SE International Way, 97222 Portland OR US | US | Heat Treating | XG | |
| TBD | IMR KHA-Portland LLC | 5687-A SE International Way, 97222 Portland OR US | US | Mechanical Testing Specimen Preparation | Z, Z3, Z4 | |
| TBD | IMR KHA-Portland LLC | 5687-A SE International Way, 97222 Portland OR US | US | Chemical Testing | F2, F3, G1, G2, G3, G4, G5 | Ti Base, Fe Base High Alloy, Fe Base Low Alloy, Al Base |
| TBD | IMR KHA-Portland LLC | 5687-A SE International Way, 97222 Portland OR US | US | Corrosion | Q | |
| 931052 | IMR Test Labs Inc. | Lansing Business & Technology Park, 131 Woodsedge Drive, Lansing New York 14882 US | US | Mechanical Testing | A, XN, N | |
| 931052 | IMR Test Labs Inc. | Lansing Business & Technology Park, 131 Woodsedge Drive, Lansing New York 14882 US | US | Mechanical Testing Specimen Preparation | Z, Z3, Z4 | |
| 931052 | IMR Test Labs Inc. | Lansing Business & Technology Park, 131 Woodsedge Drive, Lansing New York 14882 US | US | Hardness Testing | M1, M2 | |
| 931052 | IMR Test Labs Inc. | Lansing Business & Technology Park, 131 Woodsedge Drive, Lansing New York 14882 US | US | Corrosion | Q, Q1 | |

| | | | | | | | |
|------------|--|--|----|---|---|--|---|
| 931052 | IMR Test Labs Inc. | Lansing Business & Technology Park, 131 Woodsedge Drive, Lansing New York 14882 US | US | Metallography and Microindentation | L5, L5X, LS, L2, L3, L6, L7, L10, L9, L8, XL, L1, L | | |
| 931052 | IMR Test Labs Inc. | Lansing Business & Technology Park, 131 Woodsedge Drive, Lansing New York 14882 US | US | Chemical Analyses | G4, G5, S, F2, F3, G3, G2, G1 | NI Base, MG Base, AL Base CU Base, CO Base, TI Base, Fe Base High Alloy, Fe Base Low Alloy | |
| 0000651025 | Special Metals Wiggin - Inco Test Ltd. | Holmer RD Hereford, HR49SL UK | GB | Mechanical Testing | A, B, C, N, XN | | |
| 0000651025 | Special Metals Wiggin - Inco Test Ltd. | Holmer RD Hereford, HR49SL UK | GB | Hardness | M1, M2, M3 | | |
| 0000651025 | Special Metals Wiggin - Inco Test Ltd. | Holmer RD Hereford, HR49SL UK | GB | Metallography & Microhardness | L, LS, L10, L1, L2, L5, L7, L8, L9, XL | | |
| 0000651025 | Special Metals Wiggin - Inco Test Ltd. | Holmer RD Hereford, HR49SL UK | GB | Chemical Testing | F2, F3, G1, G2, G3, G4, G5, V2, S | Fe Base Low Alloy, Fe Base High Alloy, Ti Base, Al Base, Co Base, Ni Base, Cu Base | |
| 0000651025 | Special Metals Wiggin - Inco Test Ltd. | Holmer RD Hereford, HR49SL UK | GB | Mechanical Testing Specimen Preparation | Z, Z1, Z3, | | |
| 931060 | Institute of Aviation | Al. Kraowska 110/114 02-256 Warsaw, Poland | PL | Mechanical Testing | A, B, XA, Y, O | | |
| 0000044470 | Jean-Gallay S.A. | Plan-les-Ouates, 108 Chemin du Pont du Centenaire, Geneva, CH1228, Switzerland | CH | Metallography & Microhardness | L, L9 | | X |
| 0000044470 | Jean-Gallay S.A. | Plan-les-Ouates, 108 Chemin du Pont du Centenaire, Geneva, CH1228, Switzerland | CH | Hardness | M1, M2, M3 | | X |
| 0000044470 | Jean-Gallay S.A. | Plan-les-Ouates, 108 Chemin du Pont du Centenaire, Geneva, CH1228, Switzerland | CH | Metallographic Evaluation of welds | Welder, Electron beam, Laser, Resistance, Fusion | | X |
| 0000040319 | Jedco Inc. | 1615 Broadway 49504-2026 Grand Rapids MI US | US | Hardness | M2 | | X |
| 0000040319 | Jedco Inc. | 1615 Broadway 49504-2026 Grand Rapids MI US | US | Metallography & Microhardness | L, L7, L8 | | X |
| 0000040319 | Jedco Inc. | 1615 Broadway 49504-2026 Grand Rapids MI US | US | Metallurgical Evaluation of Welds | | | X |
| 931149 | Keighley Laboratories Ltd. | Croft House South Street Keighley West Yorkshire BD21 1EG United Kingdom | UK | Mechanical Testing | N, XN, A, Z, Examination according to internal method MT404 | | |
| 931150 | Keighley Laboratories Ltd. | Croft House South Street Keighley West Yorkshire BD21 1EG United Kingdom | UK | Metallography & Microhardness | L, L1, XL | | |
| 931151 | Keighley Laboratories Ltd. | Croft House South Street Keighley West Yorkshire BD21 1EG United Kingdom | UK | Metallographic Evaluation of welds | Welder, Fusion, | | |
| TBD | Laboratory Testing Inc. | 2331 Topaz drive, 19440 Hatfield PA US | US | Mechanical Testing | A, B, C, N, XN | | |
| TBD | Laboratory Testing Inc. | 2331 Topaz drive, 19440 Hatfield PA US | US | Hardness | M1, M2, M3 | | |
| TBD | Laboratory Testing Inc. | 2331 Topaz drive, 19440 Hatfield PA US | US | Metallography & Microhardness | L, L1, L5, XL, LS | | |
| TBD | Laboratory Testing Inc. | 2331 Topaz drive, 19440 Hatfield PA US | US | Heat Treating | XG | | |
| TBD | Laboratory Testing Inc. | 2331 Topaz drive, 19440 Hatfield PA US | US | Mechanical Testing Specimen Preparation | Z | | |
| TBD | Laboratory Testing Inc. | 2331 Topaz drive, 19440 Hatfield PA US | US | Chemical Testing | F2, F3, G1, G2, G3, G4, G5 | | |
| TBD | Laboratory Testing Inc. | 2331 Topaz drive, 19440 Hatfield PA US | US | Corrosion | Q1 | | |
| 0000027378 | Lambda Research | 5521 Fair Lane, 45227 Cincinnati | US | Mechanical Testing | | | X |
| TBD | Lehigh Testing Labs | 308 W Basin Rd 19720-6406 New Castle DE | US | Mechanical Testing | A, XN | | |

| | | | | | | |
|------------|-------------------------------------|---|----|---|--|---|
| TBD | Lehigh Testing Labs | 308 W Basin Rd 19720-6406 New Castle DE | US | Hardness | M1, M2 | |
| TBD | Lehigh Testing Labs | 308 W Basin Rd 19720-6406 New Castle DE | US | Metallography & Microhardness | L, L1, L10, L11, XL | |
| TBD | Lehigh Testing Labs | 308 W Basin Rd 19720-6406 New Castle DE | US | Chemical Testing | F2, F3, G3, G4, G5 | Fe Base Low Alloy, Fe Base High Alloy, Ti Base, Al Base, Cu Base, Zn and Cd Coatings |
| TBD | Lehigh Testing Labs | 308 W Basin Rd 19720-6406 New Castle DE | US | Corrosion | Q1 | |
| TBD | LUVAK INC | 722 Main St. Boylston, Massachusetts 01505 US | US | Chemical Testing | F1, G1, G2, G3, G4, G5, W1, W2 | Fe Base Low Alloy, Fe Base High Alloy, Ti Base, Al Base, Cu Base, Mg Base, Co Base, Ni Base |
| 0000044895 | Massachusetts Materials Research In | 1500 Century drive, West Boyston, MA 01583 | US | Mechanical Testing | A, N, XN | |
| 0000044895 | Massachusetts Materials Research In | 1500 Century drive, West Boyston, MA 01583 | US | Metallography & Microhardness | L, L1, L2, L5, L6, L7 L8, L10, XL | |
| 0000044895 | Massachusetts Materials Research In | 1500 Century drive, West Boyston, MA 01583 | US | Hardness | M1, M2 | |
| 0000044895 | Massachusetts Materials Research In | 1500 Century drive, West Boyston, MA 01583 | US | Metallographic Evaluation of Welds | Welder, Electron beam, Laser, Resistance, Fusion | |
| 0000044895 | Massachusetts Materials Research In | 1500 Century drive, West Boyston, MA 01583 | US | Chemical Testing | F2, G1, G2, G3, G4, G5 | |
| 0000041643 | Metals Technology Inc. | 19801 Nordhoff St, 91324 Northridge California US | US | Mechanical Testing | A, B, C, N, XN | |
| 0000041643 | Metals Technology Inc. | 19801 Nordhoff St, 91324 Northridge California US | US | Hardness | M1, M2 | |
| 0000041643 | Metals Technology Inc. | 19801 Nordhoff St, 91324 Northridge California US | US | Metallography & Microhardness | L, L1, L2, L3, L5, L6, L7, L8, XL, L10 | |
| 0000041643 | Metals Technology Inc. | 19801 Nordhoff St, 91324 Northridge California US | US | Heat Treating | Specimen Heat Treating | |
| 0000041643 | Metals Technology Inc. | 19801 Nordhoff St, 91324 Northridge California US | US | Mechanical Testing Specimen Preparation | Z | |
| 0000041643 | Metals Technology Inc. | 19801 Nordhoff St, 91324 Northridge California US | US | Chemical Testing | F3, G1, G2, G3, G4, G5, | Fe Base Low Alloy, Fe Base High Alloy, Ti Base, Al Base, Cu Base, Co Base, Ni Base |
| 0000041643 | Metals Technology Inc. | 19801 Nordhoff St, 91324 Northridge California US | US | Corrosion | Q1 | |
| 0000227663 | Metcut Research Inc | 3980 Rosslyn Dr, Cincinnati, Ohio US | US | Mechanical Testing | A, B, C, O, P, XA, XE, Y | X |
| 0000227663 | Metcut Research Inc | 3980 Rosslyn Dr, Cincinnati, Ohio US | US | Hardness | M2 | |
| 0000227663 | Metcut Research Inc | 3980 Rosslyn Dr, Cincinnati, Ohio US | US | Metallography & Microhardness | L, L1, L2, L5, L7, L8, L9 | |
| 0000227663 | Metcut Research Inc | 3980 Rosslyn Dr, Cincinnati, Ohio US | US | Mechanical Testing Specimen Preparation | Z, Z1, Z2, Z3 | |
| TBD | NSL Analytical Services Inc. | 4450 Cranwood Parkway, Cleveland, Ohio 44128 US | US | Chemical Testing | D, F2, F3, G1, G2, G3, G4, G5, S, V2, W2 | Fe Base Low Alloy, Fe Base High Alloy, Ti Base, Al Base, Cu Base, Co Base, Ni Base, Mg Base |
| 0000033963 | PCC Schlosser | 345 N. E. Hemlock Ave, 97756 Redmond OR | US | Metallography & Microhardness | L7, L9 | |
| TBD | RTI Int'l Metals Inc. | 1701 W. Main St., 63090 Washington MO US | US | Mechanical Testing | A, XN | |
| TBD | RTI Int'l Metals Inc. | 1701 W. Main St., 63090 Washington MO US | US | Metallography & Microhardness | L, L8 | |
| TBD | RTI Int'l Metals Inc. | 1701 W. Main St., 63090 Washington MO US | US | Heat Treating | XG | |
| TBD | RTI Int'l Metals Inc. | 1701 W. Main St., 63090 Washington MO US | US | Mechanical Testing Specimen Preparation | Z | |
| TBD | RTI Int'l Metals Inc. | 1701 W. Main St., 63090 Washington MO US | US | Chemical Testing | G2 | Ti Base |

| | | | | | | |
|------------|--|---|----|---|---|---|
| TBD | RTI International Metals Inc. | 1000 Warren Ave, 44446 Niles OH US | US | Mechanical Testing | A, XN | |
| TBD | RTI International Metals Inc. | 1000 Warren Ave, 44446 Niles OH US | US | Hardness | M1, M2 | |
| TBD | RTI International Metals Inc. | 1000 Warren Ave, 44446 Niles OH US | US | Metallography & Microhardness | L, L1, L5, L8, XL | |
| TBD | RTI International Metals Inc. | 1000 Warren Ave, 44446 Niles OH US | US | Heat Treating | XG | |
| TBD | RTI International Metals Inc. | 1000 Warren Ave, 44446 Niles OH US | US | Mechanical Testing Specimen Preparation | Z | |
| TBD | RTI International Metals Inc. | 1000 Warren Ave, 44446 Niles OH US | US | Chemical Testing | F3, G1, G2, G3, G4 | |
| TBD | Element Materials Technology Daleville LLC | 9301 Innovation Drive Suite 175 47334 Daleville IN | US | Mechanical Testing | A, B, C, N, XN | |
| TBD | Element Materials Technology Daleville LLC | 9301 Innovation Drive Suite 175 47334 Daleville IN | US | Hardness | M1, M2 | |
| TBD | Element Materials Technology Daleville LLC | 9301 Innovation Drive Suite 175 47334 Daleville IN | US | Metallography & Microhardness | L, L1, L2, L3, L4, L5, L6, L7, L8, L9, XL, L10, L5X, L5 | |
| TBD | Element Materials Technology Daleville LLC | 9301 Innovation Drive Suite 175 47334 Daleville IN | US | Heat Treating | XG | |
| TBD | Element Materials Technology Daleville LLC | 9301 Innovation Drive Suite 175 47334 Daleville IN | US | Mechanical Testing Specimen Preparation | Z, Z3, Z4 | |
| TBD | Element Materials Technology Daleville LLC | 9301 Innovation Drive Suite 175 47334 Daleville IN | US | Chemical Testing | D, F1, F3, G1, G2, G3, G4, G5, S, W1, W2 | Fe Base High Alloy, Fe Base Low Alloy, Mg Base, Co Base, Ni Base, Al Base, Ti Base, CU Base |
| TBD | Element Materials Technology Daleville LLC | 9301 Innovation Drive Suite 175 47334 Daleville IN | US | Corrosion | Q, Q1 | |
| TBD | Element Materials Technology Daleville LLC | 9301 Innovation Drive Suite 175 47334 Daleville IN | US | Metallographic Evaluation of Welds | | |
| 0000040230 | Special Metals Corporation | 4317 Middle Settlement Road, New Hartford 13413 NY | US | Mechanical Testing | A, B, C | |
| 0000040230 | Special Metals Corporation | 4317 Middle Settlement Road, New Hartford 13413 NY | US | Hardness | M2 | |
| 0000040230 | Special Metals Corporation | 4317 Middle Settlement Road, New Hartford 13413 NY | US | Metallography & Microhardness | L, L1 | |
| 0000040230 | Special Metals Corporation | 4317 Middle Settlement Road, New Hartford 13413 NY | US | Heat Treating | XG | |
| 0000040230 | Special Metals Corporation | 4317 Middle Settlement Road, New Hartford 13413 NY | US | Mechanical Testing Specimen Preparation | Z | |
| 0000040230 | Special Metals Corporation | 4317 Middle Settlement Road, New Hartford 13413 NY | US | Chemical Testing | D, F1, F3, G1, G4, G5, S, V1, W1, W2, G3 | Co Base, Ni Base, Fe Base High Alloy |
| TBD | Special Metals Corporation, Huntington | 3200 Riverside Dr, 25720-1771 Huntington WV US | US | Mechanical Testing | A, B, C, N, XN | |
| TBD | Special Metals Corporation, Huntington | 3200 Riverside Dr, 25720-1771 Huntington WV US | US | Hardness | M2 | |
| TBD | Special Metals Corporation, Huntington | 3200 Riverside Dr, 25720-1771 Huntington WV US | US | Metallography & Microhardness | L, L3, L7, XL | |
| TBD | Special Metals Corporation, Huntington | 3200 Riverside Dr, 25720-1771 Huntington WV US | US | Heat Treating | Specimen Heat Treating | |
| TBD | Special Metals Corporation, Huntington | 3200 Riverside Dr, 25720-1771 Huntington WV US | US | Chemical Testing | F2, F3, G1, G2, G3, G4, G5, S, V, W1, W2 | Co Base, Fe Base High Alloy, Fe Base Low Alloy, Ni Base, Cu Base, Ti Base |
| 0000614480 | Teknologisk Institutt AS | Kongsberg Naeringspark. PB. 1019, 3601 Kongsberg | NO | Hardness | M3 | |
| 0000614480 | Teknologisk Institutt AS | Kongsberg Naeringspark. PB. 1019, 3601 Kongsberg | NO | Metallography & Microhardness | L, L1, L8, L5 | |
| 0000614480 | Teknologisk Institutt AS | Kongsberg Naeringspark. PB. 1019, 3601 Kongsberg | NO | Metallographic Evaluation of welds | Welder, Fusion, | |
| 0000614480 | Teknologisk Institutt AS | Kongsberg Naeringspark. PB. 1019, 3601 Kongsberg | NO | Coating Evaluation Laboratory Practises | Metallography, Microhardness, Bond strength, Thickness. | |
| TBD | TIMET Morgantown | Industrial Pk 900 Hemlock Rd, Pennsylvania 19543 US | US | Chemical Testing | F3, G1, G2, G3, G4, S | Ti Base |

| | | | | | | | |
|------------|--|--|----|---|---|---|---|
| TBD | TIMET Henderson | Timet 181N. Water Street Henderson Nevada 89015 United state | US | Chemical Testing | F2, G1, G3, G4 | Ti Base | |
| TBD | TIMET Toronto | 100 Titanium Way, Toronto Ohio 43964-0309 | US | Mechanical Testing | A, C, XN | | |
| TBD | TIMET Toronto | 100 Titanium Way, Toronto Ohio 43964-0309 | US | Metallography & Microhardness | L, L1, L8, XL | | |
| TBD | TIMET Toronto | 100 Titanium Way, Toronto Ohio 43964-0309 | US | Heat Treating | | | |
| TBD | TIMET Toronto | 100 Titanium Way, Toronto Ohio 43964-0309 | US | Mechanical Testing Specimen Preparation | Z | | |
| TBD | TIMET Toronto | 100 Titanium Way, Toronto Ohio 43964-0309 | US | Chemical Testing | G2 | Ti Base | |
| TBD | WASA | 2-4 Hopewell Street, 6155 Canning Vale Western Australia | AU | Chemical Testing | F3, G1, G3, G4, G5, S, W1, W2 | | |
| 0000269767 | Westmoreland Mechanical Testing and Research, Inc. | Old Rte 30 Westmoreland Dr, 15696 Youngstown, Pennsylvania US | US | Mechanical Testing | A, B, C, N, O, P, XA, XE, , XN, Y | | |
| 0000269767 | Westmoreland Mechanical Testing and Research, Inc. | Old Rte 30 Westmoreland Dr, 15696 Youngstown, Pennsylvania US | US | Hardness | M1, M2, M3 | | |
| 0000269767 | Westmoreland Mechanical Testing and Research, Inc. | 221 Westmoreland Dr, P.O.Box388, Youngstown, PA 15696-0388 US | US | Metallography & Microhardness | L, L1, L2, L3, L4, L5, L6, L7, L8, L9, XL, LS | | |
| 0000269767 | Westmoreland Mechanical Testing and Research, Inc. | 221 Westmoreland Dr, P.O.Box388, Youngstown, PA 15696-0388 US | US | Heat Treating | XG | | |
| 0000269767 | Westmoreland Mechanical Testing and Research, Inc. | 221 Westmoreland Dr, P.O.Box388, Youngstown, PA 15696-0388 US | US | Mechanical Testing Specimen Preparation | Z, Z1, Z2, Z3, Z4 | | |
| 0000269767 | Westmoreland Mechanical Testing and Research, Inc. | 221 Westmoreland Dr, P.O.Box388, Youngstown, PA 15696-0388 US | US | Chemical Testing | F2, F3, G1, G2, G3, G4, G5, W2 | Mg Base, Ti Base, Cu Base, Fe Base Low Alloy, Fe Base High Alloy, Co Base, Ni Base, Al Base | |
| 0000269767 | Westmoreland Mechanical Testing and Research, Inc. | 221 Westmoreland Dr, P.O.Box388, Youngstown, PA 15696-0388 US | US | Corrosion | Q, Q1 | | |
| TBD | VSMPO | 1 Parkovaya St. Verkhnyaya Salda , 624760 | RU | Mechanical Testing | A, B, C, XN | | |
| TBD | VSMPO | 1 Parkovaya St. Verkhnyaya Salda , 624760 | RU | Hardness | M1 | | |
| TBD | VSMPO | 1 Parkovaya St. Verkhnyaya Salda , 624760 | RU | Metallography & Microhardness | L, L8, XL | | |
| TBD | VSMPO | 1 Parkovaya St. Verkhnyaya Salda , 624760 | RU | Specimen Heat Treating | | | |
| TBD | VSMPO | 1 Parkovaya St. Verkhnyaya Salda , 624760 | RU | Mechanical Testing Specimen Preparation | Z | | |
| TBD | VSMPO | 1 Parkovaya St. Verkhnyaya Salda , 624760 | RU | Chemical Testing | D, F2, F3, G1, G2, G3, G4, W1 | | |
| TBD | GS1 MUNCHE | Niederlassung SLV Munchen, SchachenmeierstraBe 37, D-80636 Munchen | DE | Metallography & Microhardness | L, L1 | | X |
| TBD | GS1 MUNCHE | Niederlassung SLV Munchen, SchachenmeierstraBe 37, D-80636 Munchen | DE | Hardness | M1, M2 | | X |
| TBD | GS1 MUNCHE | Niederlassung SLV Munchen, SchachenmeierstraBe 37, D-80636 Munchen | DE | Evaluation of welds | | | X |
| TBD | GS1 MUNCHE | Niederlassung SLV Munchen, SchachenmeierstraBe 37, D-80636 Munchen | DE | Corrosion | Q1 | | X |

| | | | | | | | |
|------------|------------------------------------|--|----|--|-----------------------------|------------------------------|---|
| TBD | GSI MUNCHE | Niederlassung SLV Munchen, SchachenmeierstraBe 37, D-80636 Munchen | DE | Chemical | F | Al & Al alloy, Fe & Fe alloy | X |
| 931086 | Outokumpu VDM USA LLC | 306 Columbia Turnpike , Florham Park New Jersey 07932 , US | US | Chemical Testing | F3, G1, G3, G4, G5, W2 | Ni Base , Co Base | |
| 931086 | Outokumpu VDM USA LLC | 306 Columbia Turnpike , Florham Park New Jersey 07932 , US | US | Metallography & Microhardness | L , XL | | |
| 931086 | Outokumpu VDM USA LLC | 306 Columbia Turnpike , Florham Park New Jersey 07932 , US | US | Hardness | M1, M2 | | |
| 931087 | Outokumpu VDM USA LLC, Reno | 14255 Mt Bismark St, Reno, Nevada 89506 ,US | US | Metallography & Microhardness | L , L8 , LS ,XL | | |
| 931087 | Outokumpu VDM USA LLC, Reno | 14255 Mt Bismark St, Reno, Nevada 89506 ,US | US | Heat Treating | XG | | |
| 931087 | Outokumpu VDM USA LLC, Reno | 14255 Mt Bismark St, Reno, Nevada 89506 ,US | US | Hardness | M1, M2 | | |
| 44617 | Binder Technologie GmbH (LAB) | Munchener Strasse 45 85123 Karlskron - Brautlach | DE | Metallographic Evaluation of Welds | Welder fusion, welder laser | | X |
| 0000012365 | Pacific Cast Technologies, Inc. | 150 Queen Avenue SW, Albany , OR 97321, United States | US | Metallographic Evaluation of Welds | | | |
| 0000012365 | Pacific Cast Technologies, Inc. | 150 Queen Avenue SW, Albany , OR 97321, United States | US | Metallography & Microhardness | L, L7, L9 | | |
| 12154 | GKN Chem-tronics El Cajon | 1150 W Bradley Avenue El Cajon ,CA 92020 , USA | US | Chemical Testing | G2 | Ti Base | |
| 12154 | GKN Chem-tronics El Cajon | 1150 W Bradley Avenue El Cajon ,CA 92020 , USA | US | Metallography & Microhardness | L,XL,L1,LS,L2,L7,L8 | | |
| 12154 | GKN Chem-tronics El Cajon | 1150 W Bradley Avenue El Cajon ,CA 92020 , USA | US | Mechanical Testing | A, XN | | |
| 12154 | GKN Chem-tronics El Cajon | 1150 W Bradley Avenue El Cajon ,CA 92020 , USA | US | Mechanical Testing Specimen Preparation | Z | | |
| 12154 | GKN Chem-tronics El Cajon | 1150 W Bradley Avenue El Cajon ,CA 92020 , USA | US | Hardness | M2 | | |